

# Dresdner, Robin & Associates

PLANNING AND ENVIRONMENTAL MANAGEMENT

195341



P.O. Box 469, 43 Montgomery St., Jersey City, New Jersey 07302 (201) 432-9800  
170 Broadway, Suite 201, New York, N.Y. 10038 (212) 619-4114

July 7, 1989

Eugene Dominach  
USEPA  
Building 209  
Woodbridge Avenue  
Edison, New Jersey 08837

Re: Ironbound Field

Dear Mr. Dominach:


Pursuant to your recent request to the City of Newark Department of Engineering, I am forwarding on their behalf the following documents pertaining to previous investigations of PCB contamination at the Ironbound Field:

- October 1987 Report of Surficial Soil Sampling conducted by Newark (DRA/Analytikem);
- January 1988 Sampling Plan prepared by NJDEP;
- June 1988 Report of Results of Surficial Soil Sampling conducted by NJDEP including Volumes 1 and 2 of laboratory data package reported by Analytikem;
- May 1989 Laboratory Results of Surficial Soil Sampling conducted by Newark (DRA and Chemical Samples & Analytical Services Co.).

Please contact Paul Butler of the Engineering Department if you have any questions.

Sincerely,

DRESDNER, ROBIN & ASSOCIATES

  
William J. Staehle

WJS:mp

cc: A. Zach  
P. Butler

Enclosure(s)

Doc. No. 115.50

# Dresdner, Robin & Associates

PLANNING & ENVIRONMENTAL MANAGEMENT

---

P.O. Box 469, 43 Montgomery St., Jersey City, N.J. 07302 ■ 201-432-9800

Mr. Eugene Dominach

USEPA

Building 209

Woodbridge Avenue

Edison, New Jersey 08837